

Liquor Store Manager Report:

Building:

Water is leaking along the side of the building into the area below the stairs going to the Attic Shoppe.
Repairs will need to be made in the spring.